

# Multiple sinkholes, drain structure in Jinjang repaired by DBKL

By **LEW GUAN XI**

lewguanxi@thestar.com.my

SINKHOLES reported earlier at Jinjang in Kepong, Kuala Lumpur, have been fixed by Kuala Lumpur City Hall (DBKL).

In a statement to *StarMetro*, DBKL said the sinkhole in Jalan Jinjang Aman 4 was caused by a collapsed wall of a nearby drain.

“The sinkholes in Jalan Jinjang Aman 5 were caused by damaged drain structure.

“Water entered the structural cracks and led to slight sedimentation of the road,” it added.

DBKL was responding to a *StarMetro* article titled

“Sinkhole danger in Jinjang” on March 17 that highlighted the residents’ concerns over three sinkholes in Jalan Jinjang Aman 4 and Jalan Jinjang Aman 5.

The local authority emphasised that it had not received any public complaints regarding the sinkholes.

It also said the sinkholes reported were small and not a danger to the public.

Repair works on the sinkholes began on March 19 and were completed recently.

In Jalan Jinjang Aman 4, the broken drain structure was repaired and the road resurfaced.

DBKL also resurfaced the road in Jalan Jinjang Aman 5.



The sinkholes in Jalan Jinjang Aman 5 have been repaired.